Certificate of Location of Government Corner

ID#: 720306 **Description:** 1/4 SEC COR 3 4 72 **Date Set:** 8/12/1991 **County:** Olmsted

Section: 03 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of fence south and 2 1/2' north of CP
County Survey Disk in W side brace post S 8.70'
Post w/sign 1' east
This corner is located by GPS measurement

Corner History:

Gov't Notes W. A. Jones 1853 North Ranilon sect.3 & 4 40.00 set a temp. sec. post south 70' E on true line between seed 3 & 4 40.18 set a sect post bur Oak 10 in. N 1/0 E 129lks.

5-1890 T. Fraser P 441 No. 427 set stake on line an d prop dist. -meas. north 40.06-3/4 (2644.45) -meas. south 39.88-3/4 2632.58 - total actual mile 79.95-1/12 5277.03

10-1894 W. Fraser P 553 No. 510 found stake P. 441. set stone 2x8x16 by its side. 1/16 west set stone M & L no meas.

3-19-1973 WHKS crew found 2"x8"x16" limestone easily near corner post. No meas. to date.

7-19-1991 County Surveyor found that corner post & stone found by WHKS (1973) was gone. There has been a dam built on the N-S line.

8-12-1991 County Surveyor set CIC/Telspar at Fraser's prorated position which matches all directions in section 4 survey. The corner falls on top of dike built in late 1980's which would have destroyed the corner.

12-6-2006 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.