Certificate of Location of Government Corner

ID#: 720409 **Description:** SEC CEN 4 72 **Date Set:** 7/5/1973 **County:** Olmsted

Section: 04 **Township:** 107N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
120d spike

Reference Ties:

Concrete nail in S side PP #20772 E 32.6'

Corner History:

10-4-1894 W. Fraser P 553 No. 510 set stone 4 x 10 x 24 at true inters lines 1/16 east set stone M & L 1/16 west set stone M & L 1/16 south set stone M & L 1/16 center SE 1/4 set stone inters lines.

1930 county highway department B62. P 12 found corner. Hub NE 52.3' - Hub SE 24.7'

1951 county highway department found limestone set drill steel riser Disc fence post NE 47.41' Disc cor. fence post E 35.45'

7-5-1973 County Surveyor removed county highway department drill steel and set 120d spike.

12-4-2006 County Surveyor visited area of corner. Found nothing. Driveway culvert falls through area of corner.