Certificate of Location of Government Corner

ID#: 720505 **Description:** SEC COR 5 6 7 8 72 **Date Set:** 9/2/2009 **County:** Olmsted

Section: 05 **Township:** 107N **Range:** 12W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is down 0.2'
The corner falls 20.5' SW of centerline of township road on curve
Concrete nail in NW side of PP #20858 NE 41.26
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: William Jones, Deputy Surveyor. North between sections 17 and 18. 80.00 chs. Set section corner post. Made mound, deposited charcoal, made trench and pits.

12-1873 Thomas Hunter (P. 236 No. 238), County Surveyor, found a stake in mound which was disputed. Set 21"x3"x3" stone as corner after measuring and running lines and considering testimony of local land owners.

5-1886 Hunter (P. 407 No. 396) found stone P. 236 in center of road.

1930 County Highway Department (Book 62 P. 7) found 4"x4"x18" limestone 4' deep. Set 1/2" pipe riser.

6-27-1973 County Surveyor dug with tractor and found 4"x4" topped limestone. Set 1 1/4"x2' pipe over stone with CIM over all.

7-30-1996 County Surveyor found CIM in good condition 12" deep in ditch slope of 65th St NE on curve.

12-11-2006 County Surveyor found CIM down 0.8' slightly leaning south.

9-2-2009 County survey crew found CIM down 0.8' leaning south. Removed and found 1 1/4"x2" pipe directly below down 2.5'. Removed and replaced with a 4' telspar pipe with cast iron cap.

7-6-2011 County survey crew found cast iron cap in good condition.