Certificate of Location of Government Corner

ID#: 720604 **Description:** 1/4 SEC COR 6 7 72 **Date Set:** 12/16/2004 **County:** Olmsted

Section: 06 **Township:** 107N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' south of centerline of CSAH 24 and 2' west of centerline of CSAH 24 south
County Survey Disk in SW side TP NW 71.36'
County highway disk in E side TP SW 67.23'
County highway disk in NE side PP #20106 SE 84.46'
County highway disk in SE PP #20105 NE 68.49'
Center of 18" Evergreen NE 85.45'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes W. A. Jones, Deputy Surveyor East on true line between sections 6 and 7 course N 89° 48' E. 38.37 chs. Set a quarter section post. Br. Oak 14 in. N51E 124 lks. Br. Oak 7 in. S56E 134 lks. 78.37 chs. To section corner.

12-1873 Tom Hunter (P. 236 No. 238), County Surveyor, found stake standing by fence corner set in earlier survey from bearing trees.

5-1886 T. Hunter (P.407 No. 396) found hole where old corner stood in center of road in line of fence running north. Set stone in place.

1930 county highway department (B.62 P.6) found (4"x6"x18"?) limestone 6" below road surface.

10-25-1974 County Surveyor dug with backhoe and found a stone 2"x10"x15" in Co. Rd. 124 2 1/2' deep. Placed large lag bolt on north side of stone and CIM over all.

7-30-1996 County Surveyor found CIM down 4" in blacktop CR#24 in good condition.

5-17-2004 County Surveyor found CIM down 0.4' in good condition.

5-24-2004 County Surveyor set reference pipes for 2004 overlay.

12-3-2004 County Surveyor set p.k. nail at surface from 2004 overlay tie-out.

12-16-2004 County Surveyor set 1" square pipe w/cap at surface over pk nail. county highway department in pp #20106 SE 84.46' and county highway department in pp #20105 NE 68.49'. Did not check any other ties.

6-22-2011 County survey crew found 1" square pipe with cap at surface in good condition.