# Certificate of Location of Government Corner

**ID#:** 720704 **Description:** 1/4 SEC COR 7 18 72 **Date Set:** 12/16/2004 **County:** Olmsted

**Section:** 07 **Township:** 107N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in centerline of CSAH 24 and 5' north of centerline of driveway west
Bottle cap in SE side TP SW 62.62'
Bottle cap in W side PP #20131 SSE 103.49'
Ref pipe SW 37.80'
This corner is located by GPS measurement

**Corner History:**

1853 Gov't Notes William Jones, Deputy Surveyor East on true line between 7 and 18. 38.63 chs. Set quarter section post. Burr Oak 10 in. N66°W 172 lks. Burr Oak 14 in. S20°W 275 lks. 78.63 chs. To section corner.

6-1876 Thomas Hunter (P. 298 No. 293), County Surveyor, states corner and bearing trees gone. Ran line from West Sec. Cor. 7-18 to Sec. Cor. 7-8-17-18 and set corner at proportionate gov't measure.

5-1886 T. Hunter (p. 407 No. 396) states corner gone. Set stone 2"x10"x20"on line and at proportionate gov't measure. Hunter (p. 408 No. 397) S S18 August Fratzke found & used stone set center road p. 407. 1/16 east set underscribed corner. 19.78 (1305.48) M & L (N89-3/4W.) Bearing S (N10'W)

5-1887 T. Hunter (P.408 No.397) found stone P. 407.

11-1891 Thomas Fraser (P. 466 No. 448), County Surveyor, found Hunter's stone. Left as found.

1957 Co. Hwy. Dept. limestone with 1" drill steel riser. Disc - tele. pole. SW 62.5 - Disc F post E 51.35 Disc F. Post W 48.18.

11-13-1973 County Surveyor dug and found Co. H.D. drill rod and recorded limestone (broken) beneath. Placed 1 1/4"x28" pipe over stone and a C.I.M. over all. Corner lies 1.8' north of a direct line between the section corners.

7-30-1996 County Surveyor found CIM 4" deep in blacktop CR #124 Set PK nail @ surface at monument location. Bottle cap in PP#20131. S.S.E. 103.49' The corner fall in centerline of CR #24 and +- 3' North of hard to see Sec. line fences E & W.

5-17-2004 County Surveyor found CIM down 0.4' in good condition.

5-20-2004 County Surveyor set reference pipe for 2004 overlay.

8-5-2004 County Surveyor removed CIM for 2004 overlay.

12-15-2004 County Surveyor set p.k. nail at surface from 2004 overlay tie-out.

12-16-2004 County Surveyor set 1" square pipe w/cap at surface over pk nail from overlay tie-out. Bottle cap in pp #20131 SE 103.49'. Did not check other tie.

6-22-2011 County survey crew found 1" square pipe with cap in good condition.