Certificate of Location of Government Corner

ID#: 720705 **Description:** W SEC COR 7 18 72 **Date Set:** 4/23/2012 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

This corner is located by GPS measurement

Corner History:

Gov't Notes Jones 1853 Set Section corner post so chains north of W 18-19 Bur Oak 10" S 88 W 115 lks. Burr Oak 8" W 78 W 112 lks. Bur Oak 4" S 80 E 23 lks. Blk Oak 6" N 21 E 129 lks.

6-1876 T. Hunter P. 298 No. 293 corner missing, all B trees gone but 1 stump, which proved correct testimony of Mr. Leary that corner post in place had replaced original stake in mound, left corner post as found.-Meas. east 38.20 (2521.2) to underscribed corner set on line and gov't prop. entire mile being 87 links short of record.-Meas. south 40.00 to stone placed on gov't stake site.

5-1886 T. Hunter P. 407 No. 396 found corner post in place - left as is P. 298-Meas. east 38.20 (2521.2) to stone 2 x 10 x 20 set this survey. (N89-3/4°)-Meas. north 39.91 (2634.06) to stake set M & L set this survey. (S1/4° E)

5-1886 T. Hunter P. 408 No. 397. found corner. post of O'Learys-Meas. easts 38.20 to stone (N89-3/4°W)

11-1891 Thos. Fraser P.466 No.448 found corner post P 298-407-408. 1/16 south set stake 20.00 M & L for line east. 1/16 east set stake on line and gov't prop. 18.41- then 19.76 total meas. for mile east 77.68-1/2 record 78.63 making west half. 38.17 east 39.51-1/2

11-14-1973 County Surveyor ran and meas. line between 7 and 18 on 30' South found 6" post hole about 1' Sely of present corner post. Placed 3/4" x 15" pipe with elbow down in old post hole.

11-29-1986 Vince Fangman fd 3/4" pipe 0.6' south and 0.3' west of corner post to fences west & north. Set studded-T post 0.5' NW of pipe R.P.S. 8d nail in wood post West 15.69' 8d nail in R.R. tie post S.W. 18.43 There is a corral fence south and East of this cor. Notice 1973 corner SE'ly of C.P.

8-1-1996 County Surveyor fd pipe set by R.B. in 1973 and found and used by V.F. in 1986 Set 4' long CIC square pipe over pipe found. The corner falls .6' so. & .3° west if C.P. to fences W & N V.F. ties still there and good. There is an E-W lane fence 16' south of corner & a N-S Lane fence 21' East of Corner.

7-6-2011 County survey crew found cast iron cap on telspar pipe leaning west in cultivated field.

4-23-2012 County survey crew found leaning telspar pipe with cast iron cap. Removed and reset using previously measured GPS coordinates. Monument is down 1'.