Certificate of Location of Government Corner

ID#: 720805 **Description:** SEC COR 7 8 17 18 72 **Date Set:** 10/16/96 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 3' north of fence west and 2 1/2' west of fence north
Spike in Twin Oak NW 36.20'
County Survey Disk in brace post SW 4.18'
Post w/sign 2' south

Corner History:

Gov't Notes W. A. Jones North 17 & 18 80.00 set at corner post to section 7,8,17,18 Bur Oak 8 in. N 9 W 158 lks Bur Oak 8 in. N 21 E 92 lks. Made a trench.

6-1876 T. Hunter P. 298 No. 293 found stone planted at fence corner, tested by B tree stumps. - Meas. west 39.56 (2610.96) to N1/4 18 when 38.20 (2531.2to twp line corner.

5-1886 T. Hunter P 407 No. 396 found stone P. 298 tested stamp NW B tree
-Meas north 40.08 to marked corner post in mound.

5-1886 T. Hunter P 408 No. 397 found stone set P 407 below.
-Meas. south 39.93 (due north) (2635.38)
-Meas west to undescribed 1/16 cor. 19.78 (1305.48) (N89-3/4°W)

11-1891 Thomas Fraser P466 No. 448 found hunters stone P408 - Meas West 39.51 (2607.66) then 19.76 (1304.16) and 18.41 (1215.06) Sec. 1/4 7/18.

5-1933 J. Kerr B8 P77 corner came 8.1' north of twin burr oak treees. No description of corner or measure from it.

11-13-1973 County Surveyor found 4"x7" topped stone at least 2' long set irons on East and West sides. Meas. west 2602.41 (R. Hunter 2510.96 TF 2607.99) 26.75 N to center blazed 8"burr oak with bussell 36.15 Nwly to 20D SW side easterly of turn burr oaks lightly blazed.

10-16-1996 County Surveyor found stone 4x7x24 with irons on E & W sides. Pulled stone and set CIC/4' long telspar pipe in its place. The corner falls 3' north of fence west 2 1/2' west of fence north. Set sign and post 2' south of monument, (1973) spike tie in Twin Oak NW 36.20', CSD in brace post SW 4.18'