Certificate of Location of Government Corner

ID#: 721205 **Description:** SEC COR 11 12 13 14 72 **Date Set:** 3/2/2009 **County:** Olmsted

Section: 12 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1 1/2' west of CP to fences N-S-E and in line with fence east
County Survey Disk in N side 24" Red Oak NW 6.45'
County Survey Disk in E side 24" Oak SSW 14.14'
Post w/sign 1 1/2' east
This corner is located by GPS reference stations "Zorro H & I"

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 13 and 14. 80.00 chs. Set post. Corner to Secs. 11-12-13-14 from which a Blk. Oak 11 in. diam. N10° W 45 links a Burr Oak 20 in. diam. N55°E 39 links a Burr Oak 10" diam. S67°E 109 links a Burr Oak 9" diam. S78°W 121 links

6-12&13-1893 William Fraser, County Surveyor, (Book A, Page 516) No. 482) "found stone with stake by its side. Drove new stake and planted another stone 18"x18"x2". This point has always been used as the corner as is claimed to be where the old Governmnet corner stood. Left as found. He used this corner to set stakes at the 1/16 East, the 1/64 East, and a point midway to the 1/64 East; the 1/16 being midway (19.93 1/2 chs.) and on line to 1/4 corner 12-13. At the 1/16 South he found a stone said set by Hillman in an earlier day.

6-26&27-1893 William Fraser (Book A, Page 518, No. 484) "Found stone and stake as recorded in Survey No. 482." He used this corner to set 1/4 Cor. 11-12, a stone boulder 20"x12"x8" midway (39.75 chs.) and on line to Sec. corner 1-2-11-12 and to set 1/4 Cor. 11-14, a stone boulder 16x12"x8" with a 12"x8"x2" limestone on top, midway (39.94 chs.) and on line to Sec. corner 10-11-14-15. He set an 18"x8"x6" boulder at the 1/16 West, an 18"x8"x3" stone at the 1/16 North, and a boulder at the 1/16 North of 1/4 corner 11-12.

6-29-1893 William Fraser (Book A, P.519, No. 485) found corner as given in Survey No. 484 and corner at the 1/16 West also given in Survey No. 484.

7-1933 County Highway Department Book 73, Page 72) found stone at the SE corner Sec. 11.

7-17-1973 County Surveyor found both stones set by Fraser in place and badly shattered.

10-26-1981 County Surveyor found shattered stones found in 1973 with a large spike in center. Drove a telspar pipe with Cast Iron Cap at the spike location and left up 1'. A large limestone (up 1') stands .5 South of the monument as a guard. This corner is 1' West of the corner post to fences N-S-E.

11-11-1981 County Surveyor dug on the south side of the CIC to be sure line from SW 11 over a point at the S1/4 corner 11 at our 1973 measure (2644.2) from center 14 (which came 1.7 south T.S.'s pipe) is covered. Line at 11-12-13-14 would then fall 3.4'+- south. Dug here under fence and East 3' but did not find anything.

8-14-2007 County Surveyor found cast iron cap on telspar pipe up 1.2' leaning north.

3-2-2009 County Surveyor removed telspar pipe w/CIC and set CIM over 1/2" rerod up 0.1' from GPS and traverse data.