Certificate of Location of Government Corner

ID#: 721206 **Description:** 1/4 SEC COR 11 12 72 **Date Set:** 11/12/1981 **County:** Olmsted

Section: 12 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 5' west of centerline of N-S twp road
County Survey Disk in E side PP #33171 NW 90.60'
County Survey Disk in W side PP #33172 SSW 116.28'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 11 and 12. 40.00 chs. Set a quarter section post from which a Burr Oak 12 in. diam. S51ºE 140 lks. Burr Oak 7 in. diam. S85ºW 79 lks.

6-26 & 27-1893 William Fraser, County Surveyor, (Book A, Page 518, No. 484) could not find this corner. Set a stone boulder 20"x12"x8" midway (39.75 chs.) and on line between the section corners. He set a stone boulder at the 1/16 North and a 18"x8"x3" stone at the 1/16 South. He set the 1/16 West, a stone 16x8x4, midway (19.97 1/2 chs.) and on line to the Center 11, a 24"x5"x2 1/2" stone, set at intersecting 1/4 lines.

6-11-1902 Robert Fraser, Deputy County Surveyor, (Book A, Page 709, No. 623 and Old Fieldbook 10, Page 44) "Found boulder stone given in previous survey. It comes West of road on bank and in line with old ridge East." He used this corner to set the Center 12, a temporary stake (a Mr. Richardson said he would put stone), set at intersecting 1/4 lines. He measured North to the 1/16 North and "Found corner stone boulder stone spoken of in previous survey. Varied 1 link from former survey." He shows a measure here of 19.87 1/2 chs.

1933 County Highway Department (C.H.D. Book 73, Page 72) found stone at the 1/16 North but found nothing at 1/4 corner 11-12 or the 1/16 South.

7-1973 County Surveyor dug at the 1/16 South and found recorded stone. Set 1/2" rod over stone at ground surface. (This stone is 1.59' South and 2.11' East of the calculated location here after 1/4 corner 11-12 and Sec. corner 11-12-13-14 are set.)

11-12-1981 County Surveyor, this corner and the 1/16 North are both in big cuts in the N-S road so we did not dig for them. Set a Cast Iron Monument over a R.R. spike as the corner midway (2620.25) and on line between the section corners. We found Fraser's stone at the Center 11 and the line projected from the W 1/4 corner 11 over said stone would fall 1.0' South of the corner as set. We also dug at the Center 12 and found a limestone and the line projected from the E 1/4 corner 12 over said stone would fall .27' South of the corner as set.

3-16-2010 County Surveyor found CIM down 0.4' in good condition.