Certificate of Location of Government Corner

ID#: 721406 **Description:** 1/4 SEC COR 14 15 72 **Date Set:** 7/12/1973 **County:** Olmsted

Section: 14 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 11 1/2' south of centerline of E-W twp road, in line with fence north and transmission pole line south
Top center of outside edge of N end of 18" smashed culvert NW 57.4'
Concrete nail in W side transmission PP S 36.65'
40d spike in top 6" Cedar CP N 35.62'
Punch hole in N end 24" CMP NW 61.20'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William Jones, Deputy Surveyor North between sections 14 and 15. 40.00 chs. Set a quarter section post. Burr Oak 8 in. N20°W 186 lks. Burr Oak 10 in. N10°E 177 lks.

6-1893 William Fraser (P. 519 No. 485), County Surveyor, found stone in place to be midway and on line.

7-12-1973 County Surveyor dug in south slope of road and found a large vertical limestone. Set C.I.M. over stone.

11-7-1996 County Surveyor found CIM on south ditch slope of 48th St NE leaning badly to the west. Dug down to bottom and straightened to original position. The top of CIM is 15" deep. Centerline E-W 48th St NE N 11-1/2'. Punch hole in north end 24" CMP NW 61.20'. The corner lines with fence line north and transmission pole line south.

6-22-2011 County survey crew found cast iron monument down 1.1 in good condition.