Certificate of Location of Government Corner

ID#: 721504 **Description:** 1/4 SEC COR 15 22 72 **Date Set:** 6/2/2008 **County:** Olmsted

Section: 15 **Township:** 107N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 47' east of centerline of TH 42 and 4 1/2' south of centerline of twp road east
County Survey Disk in SW side PP SE 75.65'
County highway disk in NE side TCM brace post SE 41.06'
County Survey Disk in W side PP NNE 56.82'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 15 and 22. 40.05 chs. Set a quarter section post in mound of earth and sod, deposited charcoal, made trench and pits and planted Osage orange seed North and South of the trench.

5-1872 S. Hillman (1890 letter on record), a surveyor, set the Center of Section 22 so apparently found this corner. Minn. Hwy. R/W map for TH 42 shows the center of the old intersection, taken as the 1/4 corner, is approx. 45' East of the present centerline.

11-18-1976 County Surveyor dug with the backhoe but found no evidence of the corner.

11-19-1976 County Surveyor set a C.I.M. over a 1/2"x2' rod as the corner at double the line and measure from the Center of Section 22 (found) over the 1/16th North (found).

12-7-1989 county highway department found CIM checked RP's, CSD in PP NE 60.05', county highway department disc in tele pole SE 41.39'.

11-7-1996 County Surveyor Blacktopping of TH 42 has covered corner with ±6" of blacktop. We checked ties and dipped CIM. Set P.K. nail at CIM location. Will set pipe at surface after last lift is applied.

5-16-1997 County Surveyor set 1" square pipe w/cap at surface over pk nail.

1-3-2007 County survey crew found 1" square pipe w/cap at surface in good condition.

5-9-2008 County survey crew found 1" square pipe w/cap at surface in good condition. Updated ties.

5-14-2008 County survey crew found 1" square pipe w/cap at surface in good condition. Took ties and removed. Found CIM down 0.9' in good condition. Took ties and removed. Found 1/2" rod down 2.1' in good condition. Will set new monument when blacktop hardens.

6-2-2008 County survey crew set 1" square pipe w/cap at surface from local ties.

6-22-2011 County survey crew found 1" square pipe with cap in good condition.

7-7-2016 County survey crew found 1" square pipe with cap in good condition.