Certificate of Location of Government Corner

ID#: 721606 **Description:** 1/4 SEC COR 16 17 72 **Date Set:** 8/17/10 **County:** Olmsted

Section: 16 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.5'
The corner falls 4' west of centerline of CR 102
County Survey Disk in S side RR tie CP W 28.05'
County Survey Disk in E side PP #39253 SW 84.00'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 16 and 17. Set a 1/4 corner post midway and on line (40.00 chs.) Burr Oak 10" N78°W 182 lks.
Burr Oak 8" N53°E 40 lks.

7-1870 Robert Perry (P.130 No. 162), County Surveyor, states all bearing trees gone. Found a stone set by neighbors which was just close because the original stone had been lost by the road crew. Set a stone 2"x3 1/2"x20 with small stones on the west side as witnesses, midway and on line. Removed the other stone set as corner.

5-1933 John Kerr (Book 8 P. 77), County Surveyor, set a limestone 2"x2" on top by 14" long packed in broken rock with a 5/8"x10" iron bolt below in line with east-west fences. Set stone midway and on line.

5-23-1974 County Surveyor found Kerr's stones and bolt 3' deep.

5-28-1974 County Surveyor set a C.I.M. over a 3/8" pipe 8" long. Corner falls in west wheel track of the north-south township road.

8-17-2010 County survey crew found CIM down 0.5' leaning. Measured ties and removed. Found 3/8" pipe directly below. Measured ties and removed. Found 5/8" bolt directly below down 3.1' in good condition. Set telspar pipe with cast iron cap down 0.5' at bolt location.