Certificate of Location of Government Corner

ID#: 721704 **Description:** 1/4 SEC COR 17 20 72 **Date Set:** 12/7/89 **County:** Olmsted

Section: 17 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls in centerline of CSAH 2
County highway disk in stub TP NW 147.06'
County highway disk in PP SW 74.70'
Ref pipe SSE 117.40'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: W.A. Jones. East random between 17 & 20. 40.00 set a temp sec post west on true line between sect 17 & 20 Var 8° 58' E. 40.03 set a temp sect post in mound of earth and soil deposited charcoal, made trench and pitts, planted Osage Orange seed N and S of trench.

5-1886 T. Hunter P.409 No.398 found stone planted in center road as corner. Meas west 40.16 to stone found 2650.56. Meas east 39.90 to stone found 2633.4.

6-1903 C. Armstrong P.60B John Daly found stone cener road, 2 feet west of row of trees running south. Meas west 40.06 to stone found 2643.96. Meas east 39.78 to stone found 2625.48.

6-1924 county highway department B.42 P.10 found stone 4x4x10 and oak stake. Meas east 2634.1, meas west 2651.2

5-1933 J. Kerr B.8 P.77 found iron pipe riser over stone (Co. Hwy. Dept) 1/2" pipe 33' south. Meas east 2632.5 to NE 20.

4-1939 county highway department Book 106 page 2, found 1" pipe top of limestone.

5-18-1964 J. Kerr used corner set CIM over pipe limestone still near corner as proof witness B.88 P.19. Spike in 10" Oak S 73.2'. Disc tele pole NE 87.5' lies in center blacktop road.

8-8-1986 County Surveyor set 3/4" pipe w/cap as transit tie to 1/4 cor. Pipe is ± 118' S of centerline Co. Rd #2 and in field dr. S ± 12' E of N-S fence. Angle at 3/4" pipe angle RT 115° 16' 13" most northerly and shortest radio tower to 1/4 cor 17-20 pipe to 1/4 cor 117.40'.

8-11-1986 County Surveyor replaced CIM with 1/2" iron

12-7-1989 county highway department set 5/8" brass plug in centerline CR #2. RP's: county highway department disc in stub tele pole NW 147.06'. county highway department disc in PP SW 74.70'

7-30-2002 County Surveyor found 5/8" brass plug at surface in good condition.