Certificate of Location of Government Corner

ID#: 721806 **Description:** W 1/4 SEC COR 18 72 **Date Set:** 3/11/2009 **County:** Olmsted

Section: 18 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface.
The corner falls 6' north of CP to fences E-W-S and 1 1/2' east of fence south
This corner is located by GPS reference station "PN A & B"
Pk nail in W side CP SW 6.10'
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor North between sections 13 and 18. 40.00 chs. Set quarter section post. Burr Oak 10 in. S78°E 260 lks. Burr Oak 10 in. N 76°E 204 lks.

6-1876 Thomas Hunter (P. 298 Book A), County Surveyor, found stake and tested by stump of S.E. witness tree. Set stone 4"x4"x20".

5-1886 T. Hunter (P. 408 No. 397) found stone P. 298.

11-1891 Thomas Fraser (P.466 No. 448), County Surveyor, found stone set by Hunter P. 298.

1937 Co. H.D. (Book 92 P. 78) found 5" square limestone at fence corner and 8" of stone broken off lying by corner post.

11-7-1973 County Surveyor found 5" square topped limestone about 14 in. long 2' north of the corner post.

11-12-1973 County Surveyor set C.I.M. over 1/2" rod with original stone on north side.

9-21-2006 County Surveyor found top portion of CIM lying flat 7' south of corner post. Did not find anything else. Set 2 pts. to determine final location.

3-11-2009 County survey crew found broken CIM down 0.8'. Took local ties and removed. Found 5/8" iron rod down 1.6' in good condition. Set 5' telespar pipe w/CIC over rod at surface.

9-30-2010 County survey crew found CIC in good condition.