Certificate of Location of Government Corner

ID#: 721906 **Description:** W 1/4 SEC COR 19 72 **Date Set:** 6/27/2011 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 3 1/2' west of centerline of N-S twp road and 6' south of fence east
The monument is down 0.5'
USGS Survey Marker "Gates" ENE 28.71'
County highway disk in PP #19438 NNE 124.57'
This corner is located by GPS measurement

Corner History:

Gov't Notes: 40.00 set post for 1/4 section corner. Bur Oak 6 N1°W 16. Bur Oak 10N5°E 84.

7-1874 T. Hunter P.258 No.259 corner gone searched by digging. Set stone 4x8x26 M&L 39.96-1/2 (2637.7) N 5' W. 1/16 east set temp stake 18.44 on line then 19.65 to center 19 for line south set by proportion as further south. 1/16 west set temp stake M&L 19.91 S89° 50 W for line S. Set 1/16 corners center SE 1/4 24 and SW 1/4 19 by inters lines. Witness to 1/16 cor center SE 1/4 24. 24 lks north to small oak tree in fence.

1937 county highway department B92 P.78 dug found nothing assumed corner. Set 1-1/2" tubular steel post. Co. set assumed corner on range line from W 1/4 18 (stone) south to SW 19 2636.93 1/3 total meas. Disc cor F post E 29.55. Disc cor F post NE 46.75. Center C. Geo mon ENE 27.25.

9-10-1968 County Surveyor found limestone as recorded. Set CIM over 1 1/4" pipe.

6-13-2002 County Surveyor found CIM without head down 1.1' in good condition.

7-11-2002 County Surveyor set cast iron cap on telspar pipe at CIM location.

4-25-2007 County Surveyor found telspar pipe with no cap split at surface. Dug down and cut pipe. Set CIC on pipe down 0.5'. Updated ties.

6-27-2011 County survey crew found telspar pipe down 0.4' with top portion bent. Removed and replaced with a 5' telspar pipe and cast iron cap in the same hole.