Certificate of Location of Government Corner

ID#: 722105 **Description:** SEC COR 20 21 28 29 72 **Date Set:** 4/21/88 **County:** Olmsted

Section: 21 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.6'
The corner falls 8.3' east of N-S fence which bows out for creek
Spike in 18" Burr Oak SE 71.49'
Spike in NW side Maple cluster (4' dia 6 trunks) NE 21.53'
Post w/sign 3 1/2' west
This corner is located by GPS reference stations

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 28 and 29. 80.00 chs. Set a section corner post. Burr Oak 10 in. N42°W 182 lks. Burr Oak 17 in. N9°E 360 lks.
Burr Oak 20 in. S20°E 100 lks. Burr Oak 9 in. S8°W 191 lks.

5-1886 Thomas Hunter (P. 409 No. 398), County Surveyor, found original stake standing by fence in slough. Tested with S.W. bearing tree and stump (marked) of S.E. bearing tree.

3-1896 William Fraser (P. 593 No. 589) found stake corner of page 409.

6-1902 Charles Armstrong (Book B Page 58), County Surveyor, states corner washed out. An Albert Newman avers fence running north is in line with old stake. No description of corner.

5-28-1974 County Surveyor reset the corner at the intersection of the east line of Sec. 29 projected north and the North line of Section 28 projected west. Drove a 5' long 1 1/4" iron shaft as the corner with 6" of the shaft above ground.

4-21-1988 Roger Brand & Associates trav revealed shaft set in 1974 was not placed at intended location. Dug in spot 7.23 E and .2 S found N-S fence and post lying down 2-1/2' deep by 4' diameter. Set CIC/ 6' telspar at location since it was on line from the SE cor 21 over the S 1/4 cor 21 as per W.F. survey No.589 and it came in old fence line as recorded by Hunter in survey No.398 and mentioned by Armstrong in survey R 58 B, cor is in line with fence running both farther north and south its 8.3 centerline of N-S fence by cor which bows west around creek. Set sign and post 3.35 west removed old shaft. RP's: Spike in NW side maple cluster (4' diam 6 trunks) NE 21.53'. Spike in E'ly side 18" Burr Oak with old 1974 blaze SE 71.49'.

8-19-2010 County survey crew found cast iron cap in telspar pipe in good condition.