Certificate of Location of Government Corner

ID#: 722205 **Description:** SEC COR 21 22 27 28 72 **Date Set:** 6/14/2011 **County:** Olmsted

Section: 22 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is up 0.1'
The corner falls 13' north of E-W fence and 4' west of N-S fence
County Survey Disk in S side blazed 21" Burr Oak ESE 5.00'
County Survey Disk in N side blazed 19" Burr Oak ENE 2.31'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 27 and 28. 80.00 chs. Set section post corner to section 21, 22,27 & 28. Burr Oak 10 in. N10°W 29 lks. Burr Oak 9 in. N70°E 62 lks. Burr Oak 15 in. S40°E 130 lks. Burr Oak 8 in. S15°W 15 lks.

5-1872 S. Hillman (1890 letter on record), a surveyor, replaced stake with a 24" stone.

3-1896 William Fraser (P.593 No. 589), County Surveyor, found a stone and the location of the former S.W. bearing tree which proved the stone correct. A Mr. Cunningham avered that settlers Removed the original stake and placed the stone in its place.

5-26-1974 County Surveyor found a 1"x10" topped limestone. Set a bolt on the South edge of the stone and a steel fence post on the West side.

11-1-1976 County Surveyor found the stone found 5-28-1976. Removed the top 10" of the stone which was broken and set a C.I.M. over the remainder. Drove the bolt on the North edge of the stone and set the Top piece of the stone on the South side of the C.I.M. Set 3 reference ties.

12-19-1986 County Surveyor found CIM tilted east and ground frozen. Oak tree 12.19' north is gone.

6-14-2011 County survey crew found broken and leaning CIM. Also found bolt leaning. Removed bolt and CIM and found no other monument. Set a 5' telspar pipe with cast iron cap using the 2 remaining reference ties from 1976.