Certificate of Location of Government Corner

ID#: 722209 **Description:** SEC CEN 22 72 **Date Set:** 11/8/1976 **County:** Olmsted

Section: 22 **Township:** 107N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" pipe w/stone on S side

Reference Ties:

The corner falls 42 1/2' east of centerline of TH 42, in line with fence east and 50' south of centerline of cattle pass
County Survey Disk in N side CP E 31.92'
Concrete nail in top center 24" RCP NNE 23.26'
County Survey Disk in SE side TP with box NE 57.91'
This corner is located by GPS measurement

Corner History:

11-8-1976 County Surveyor dug in E ditch of Hwy 42. Found stone (broken) 3' 5" long x 3" thick x 13" wide. Unbroken part standing 3' deep. Drove long pipe on W side top of pipe down approx 1'. This stone set by Silas Hillman in 1872 and recorded in letter of 1890 on file. Corner in line with fence E, 50' S center of cow pass under Hwy 42, and 42.6' E of centerline Hwy 42. RP's: Concrete nail top center 24" concrete culvert NNE 23.26'. CSD SE side telephone pole with box NE 57.91'. CSD N side corner post to fence E E 31.92'.

11-18-1976 County Surveyor at 1/16th corner north dug in E ditch of Hwy 42. Found 2" x 3"/ 8" x 24" stone (leaning 45° to west) straightened stone. Top down 1' corner 3' south of line of fence E and in line with fence W.

11-19-1976 County Surveyor at 1/16th corner north broke off stone and set 1-3/4" x 18" pipe over remainder with piece on S side. RP's: CSD N side CP ENE 30.42'. Punch mark (up 6") W side R/W post SE 43.7'. Center line of TH 42 west 45.27'.

10-3-1990 Roger Brand & Associates found and used 1" pipe at center of section 22.

7-18-1991 Roger Brand & Associates found and used 1" pipe at center of section 22.

2-26-1999 Roger Brand & Associates found and used 1" pipe at center of section 22.

1-9-2007 County survey crew found 1" pipe in good condition.

5-9-2008 County survey crew found 1" pipe down 0.4' in good condition.

6-22-2011 County survey crew found 1" pipe down 0.6' in good condition

7-7-2016 County survey crew found 1" pipe down 0.4' in good condition