Certificate of Location of Government Corner

ID#: 722304 **Description:** 1/4 SEC COR 23 26 72 **Date Set:** 6/16/2008 **County:** Olmsted

Section: 23 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of fence south and 1' north of E-W fence
County Survey Disk in ESE side 36" Oak up 1' NNE 19.23'
County Survey Disk in N side huge triple Oak up 0.8' ESE 36.69'
Post w/sign 2' west
This corner is located by GPS reference stations "T. Dub A & B"

Corner History:

1853 Gov't Notes West between sections 23 and 26. 40.01 chs. Set a quarter section post. Burr Oak 9 in. N32°W 97 lks. Burr Oak 14 in. S67°W 159 lks. 42.00 chs. Stream 3 lks. wide runs NE.

No other known records of this corner.

8-16-1973 County Surveyor dug in area of corner and found dark spot in subsoil which came .4' south and .4' east of midway and on line. Set 3/4 length CIM over a 1/2"x15" rod over the dark spot.

5-14-2008 County survey crew found CIM down 0.2' leaning NW, took local ties and removed. Found 1/2" iron rod down 1.8' in good condition, checked local ties. Reset 3/4 length CIM over rod. Updated ties.

6-10-2008 County Surveyor decided to conduct further investigation of this corner because the current location is 9' east of of the fence corner. County survey crew excavated by hand near the fence corner and found a limestone 2" x 7" x 11" in an upright position down 1.8'. The stone falls 1' N and 1' E of corner post for fences south and east. Center of stream W 145 1/2'. The position of the stone also fits the fence corner at the center of Section 26-107-12. The County Surveyor decided the found limestone is the best perpetuation of the original corner position.

6-16-2008 County survey crew replaced the 2" x 7" x 11" limestone with a 4' telspar and cast iron cap up 0.4'. Found the CIM 9' east and removed.