Certificate of Location of Government Corner

ID#: 722405 **Description:** SEC COR 23 24 25 26 72 **Date Set:** 6/10/2008 **County:** Olmsted

Section: 24 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' west of centerline of N-S twp road and 2' south of fence east
SE cor. new house foundation NW 137.6'
County highway disk in N side PP #569 SW 39.21'
County highway disk in N side PP #43526 ENE 38.84'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William Jones, Deputy Surveyor North between sections 25 and 26. 80.00 chs. Set section corner post. Blk. Oak 7 in. N17 1/2°W 35 lks. Burr Oak 7 in. N40°E 158 lks. Burr Oak 6 in. S75°E 206 lks. Blk Oak 6 in. S67 1/2°W 85 lks.

6-1893 William Fraser (P.514 No. 481), County Surveyor, found stone.

7-18-1973 County Surveyor dug in road and found 2"x6"x8" limestone with definite dark area below. Placed 12" farm tile above stone with 5/8" iron riser.

7-26-1973 County Surveyor set C.I.M. over stone, farm tile, and drag tooth.

NOTE: Roger Brand and Associates found and used CIM here in 1996, 1997 & 1998.

8-9-2007 County Surveyor found CIM down 0.5' with head broken off in good condition.

6-10-2008 County Surveyor found CIM w/broken head down 0.7'. Took local ties and removed. Found drain tile w/drag tooth inside down 2.3'. Took ties and removed. Found 2" x 6" x 8" stone down 3.5' in good condition. Took ties and removed. Set a 6' telspar pipe w/CIC down 0.45' at CIM location.