Certificate of Location of Government Corner

ID#: 722704 **Description:** 1/4 SEC COR 27 34 72 **Date Set:** 1/11/2007 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 28' east of centerline of TH 42, 8' north of fence east and 3 1/2' north of row of pines east.
The monument is at the surface
Post w/sign 2' east
This corner is located by GPS measurement.

Corner History:

1853 Gov't Notes: W.A. Jones, east random 27 and 34. 40.00 set a temp sect post west on true line between sect 27 and 34 Var 8° 43' E. 40.06-1/2 set a sect post. Bur Oak 7 in. N35E 144 lks. Bur Oak 7 in. S70W 204 lks.

Unrecorded survey June 2, 1885 Tom Hunter Book #14 page 39. Found stone set by me in a former survey on line and midway between SE 27 and SW 27. T.H. #42 R/W map shows 1/4 corner ± 25' east of centerline pav't along a fence line to east. There is a deep gully just south of this location. Old road bed apparently in place before grading of T.H. 42 which showed 1/4 corner was assumed to be in centerline thereof. S. Hillman loose leaf letter dated 1890 says that in May 1872 he used south qr stake sec 27 and some kind of BT Bur Oak 10 S 6-1/2°W 203 instead of Burr Oak 14 south 67 west 159 as field notes say. Says also meas west short 20 lks.

11-19-1976 County Surveyor set 3/4"x3' rod to hold M&L location. Rod on W bank of E ditch of Hwy 42. Rod 8' N of fence E and 3'1/2' N of line of pines E. N-S toll cable runs 5' E. RP's: concrete nail in guard post NW 13.17' (gone 1986). Concrete nail in guard post SW 17.50' (gone 1986). centerline Hwy 42 W 28.00'.

6-19-2002 Brand & Massey Surveying Inc. found and used 3/4" rod at quarter corner.

1-9-2007 County survey crew found 3/4" rod down 0.4' in good condition.

1-11-2007 County survey crew removed 3/4" rod and set 5' telspar pipe w/cast iron cap down 0.2'. Set post w/sign 2' E.

6-10-2011 County survey crew found cast iron cap on telspar pipe in good condition.

7-7-2016 County survey crew found cast iron cap on telspar pipe in good condition.