Certificate of Location of Government Corner

ID#: 722806 **Description:** 1/4 SEC COR 28 29 72 **Date Set:** 8/18/10 **County:** Olmsted

Section: 28 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.5'
The corner falls 1' west of centerline of N-S twp road and in line with fence east
Punch hole in N end 18" CMP E 32.00'
Punch hole in S end 18" CMP SE 41.33'
Ref. iron E 70.0'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: W.A. Jones, 40.00 set a section post. Bur Oak 7 in. N47W 230 lks. Bur Oak 6 in. N40E 65 lks.

6-1902 C. Armstrong P.58B corner gone. Set temp point midway 39.89 for line west. Dug over large area of road found nothing.

5-24-1974 County Surveyor dug with backhoe and found 2 stakes. Used the north stake which is probably the original and the other may be C. Armstrongs - C.A. stake in 5.75 S and 1.69 east of the corner we used. The N'ly stake fits the 1/4 line to the west best. Transit tie just at 1/4 cor location slighted on corner post 1/4 mile west and set a rod 70' E.

1-28-1987 County Surveyor set cast iron cap on telspar pipe ± 1' W of centerline N-S road and line of fence east RP's: Punch hole in N end 18" CMP east 31.91'. Punch hole in S end 18" CMP SE 41.37'.

8-18-2010 County survey crew found cast iron cap with telspar pipe at surface with the top portion bent. Removed the telspar pipe and found the bottom portion to be straight and plum. Set a new telspar pipe with cast iron cap in the same hole.