Certificate of Location of Government Corner

ID#: 722906 **Description:** 1/4 SEC COR 29 30 72 **Date Set:** 10/8/1974 **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 10' west of centerline of CR 102 and in line with fence east
Punch hole in top of driveway CMP N 65.07'
Punch hole in W end 28" CMP (oval) SSW 25.75'
NW corner 8" concrete CP E 42.23'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor
North between sections 29 and 30. 40.00 chs. Set a quarter section post in mound of earth and sod. Deposited charcoal, made trench and pits, and planted osage orange seed east and west of trench.

6-1873 Thomas Hunter (P. 227 No. 230), County Surveyor, states 1/4 corner missing. A Mr. E.H. Derby avers under oath he set a cedar post (still standing) 3 paces west of corner when it stood. Set a new stake by this evidence.

6-1902 Charles Armstrong (P. 58 Book B), County Surveyor, found the cedar post mentioned on page 227. Dug 4' wide and found nothing until 14' east of post. Not knowing if post had been moved or if 3 paces would cover 14', ran the north-south line of 29 and 30. Midway and on line point fell just 14 1/2' east of the cedar post in due line of fence west. Set a limestone 5"x 14"x26" midway and on line.

5-22-1974 County Surveyor reset this corner midway and on line at 2642.95' because it fell under a 24" road culvert. Dug under culv., but could not identify any stone among the many there.

10-8-1974 County Surveyor set a C.I.M. over a 3/4"x18" rod as the corner since county highway department had moved culvert location further south.

6-11-1980 county highway department found CIM and took ties.

7-10-2002 County Surveyor found CIM in good condition.