Certificate of Location of Government Corner

ID#: 723104 **Description:** S 1/4 SEC COR 31 72 **Date Set:** 6/30/2005 **County:** Olmsted

Section: 31 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" brass plug with punch mark

Reference Ties:

The corner falls 0.2' north of centerline of CSAH 9 and 1' west of fence north
Punch hole in W end 18" CMP SW 48.08'
County Survey Disk in W side PP SW 60.60'
3/8" iron N 100.0'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 6 and 31. 40.00 Set post and drove charred stake. Built mound with trench. Planted plumb SE and apple seed NE 78.05 to township corner.

5-1871 Thomas Hunter (P. 184 No.195), County Surveyor, found stake in center of road. Mound and pits still visible.

5-1872 T. Hunter (P. 206 NO. 214) found stake in center of road. Set stone 4"x8"x16".

1937 County Highway Department (B. 88 P. 12 and P. 76) found limestone.

6-2-1970 County Surveyor dug through black top and subbase and found a limestone with 6" stake hole beneath. Placed a 1"x4' steel mop handle in hole with original stone pieces on east and west sides. Set 1/2"x2' rod near road surface.

11-19-1974 County Surveyor found County Highway Department P.I. Rod at corner. Accepted as corner after checking with R.P.'s.

An analysis of the historic record indicates that this corner is a perpetuation of the Original Public Land Survey.

7-15-2003 County Surveyor found copper plug with punch mark at surface in good condition.

6-30-2005 County Surveyor set brass plug with punch mark at surface from coordinates. Monument falls .21' north of centerline crack of CR 9 and 1.0' west of fence north. CSD with concrete nail in west side of PP no # SW 60.60', punch hole in top lug clamp west end 18" CMP SW 48.08', other end had been hit. Did not try to locate reference iron.

4-27-2009 County Surveyor found 5/8" brass plug w/punch mark at surface in good condition.