Certificate of Location of Government Corner

ID#: 723204 **Description:** S 1/4 SEC COR 32 72 **Date Set:** 6/30/2005 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" brass plug with punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9 and in line with fences north and south
Angle iron CP N 67.28' (leaning north)
Punch hole in W end 18" CMP S 45.19'
Punch hole in W end 18" CMP NW 51.99'
Punch hole in E end CMP SE 51.20'
Reference iron N 100.0'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor
West between sections 5 and 32. 40.00 Set post and drove charred stake for quarter section corner. Built mound with trench and planted plumb SE and apple seed NE.

6-1873 Thomas Hunter (P. 226 No. 229), County Surveyor, dug in center of road and found badly rotted stake.

1937 County Highway Department (B. 88 P. 12 and 76) found cedar stake.

6-1970 County Surveyor dug in road and found limestone with wood stake on east side. Set 1"x 2" wood hub where old stake was and 1-1/2"x20" iron pipe on west side. Set 1/2" x 2' iron rod near road surface. Placed 1/2"x2' rod 100' north on transit line to steel posts of fence line approx. 2000' north after fence comes out of low area.

11-20-1974 County Surveyor set a 1-1/4" pipe as corner using 1970 transit ties.

An analysis of the above record indicates that the 1-1/4" pipe is the perpetuation of the Original Public Land Survey.

7-15-2003 County Surveyor found 1 1/4" pipe at surface in good condition.

6-30-2005 County Surveyor set a brass plug with punch mark at surface. The monument falls 0.1' north of CR 9 and in line with fences north and south. Rechecked all other ties and updated distances, did not try to located reference iron and iron corner post was leaning, did not recheck tie.

4-27-2009 County Surveyor found 5/8" brass plug w/punch mark at surface in good condition.