Certificate of Location of Government Corner

ID#: 723205 **Description:** S SEC COR 31 32 72 **Date Set:** 6/30/2005 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" brass plug with punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9, 1 1/2' east of centerline of CR 102 north and 1 1/2' west of centerline of CR 102 south
County highway disk in SE side PP #42511 SW 70.83'
County highway disk in NW side PP #42510 SE 72.34'
County highway disk in NW side PP # 20459 NE 86.19'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 5 and 32. 80.00 chs. Set post and drove stake. Built mound with trench. Planted plumb S.E. and apple seed N.E.

5-1871 Thomas Hunter (P. 184 No. 195), County Surveyor, found stub of old stake 8" deep. Set boulder in its place.

5-1872 T. Hunter (P. 206 No. 214) found stake in center of road.

5-1873 T. Hunter (P. 226 No. 229) found stake.

1937 County Highway Department (B.88 P. 76) found cedar stake.

6-3-1970 County Surveyor dug in center of road and found hub set by County Highway Department in 1937. Set 3/4" x 15" rod in remains of old hub still down 8" in clean clay. Set 1/2" x 2' rod in new black top.

11-19-1974 County Surveyor found county highway department P.I. rod at corner location so accepted as corner.

6-11-1980 county highway department found 1/2" re-rod and took ties.

An analysis of the historic record indicates that this corner is a perpetuation of the Original Public Land Survey.

7-15-2003 County Surveyor found copper plug with punch mark at surface in good condition.

6-30-2005 County Surveyor set a brass plug with punch mark at surface from coordinates. The monument falls 0.1' north of centerline of crack of CR 9, 1.5' east of road north and 1.5' west of centerline of road south. Rechecked all other ties and updated distances.

4-27-2009 County Surveyor found 5/8" brass plug w/punch mark at surface in good condition.