Certificate of Location of Government Corner

ID#: 723206 **Description:** 1/4 SEC COR 31 32 72 **Date Set:** 5/19/2006 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of CR 102 and 2' south of centerline of field entrance west
This corner is located by GPS reference stations "Madden A & B"

Corner History:

1853 Gov't Notes: W.A. Jones, 40.00 set a section post in mound of earth and sod. Deposited charcoal, made trench and pitts, planted Osage Orange seed E and W of trench.

9-1863 P.C. Compton P.77 No.114 shows 1/4 corner used to set center sec 31 at intersecting lines.

5-1872 T. Hunter P.206 No.214 gone, no evidence or knowledge. Set temp point M&L 39.84-1/2 for line west.

6-1873 T. Hunter P.226 No.229, corner gone renewed search for corenr or knowledge of it. Set stake M&L 39.84-1/2 for line east S10'E. 1/16 north set stake M&L 19.92-1/4 for line east S10'E line east due east and west

11-1968 J. Kerr Book 98 P.37, meas N-S line 5263.5 A 5258.88 R (set 1/2" steel rod 2631.75?). 1/16 fence east north to section stone and CIM 1314.2A 1314.7R no fence east and fence west on common land about 2646.2 from south instead of 2631.75. Set temp point 14.45 south and run aerial over angle iron corner post as center 32. Line came about 4 feet north of midway on east line 32 indicating either center or W 1/4 needs adjusting meas east line twice.

6-11-1980 county highway department found 1/2" re-rod and took ties.

6-2-2005 County Surveyor dug with backhoe in N-S CR 102 for stake set by T. Hunter midway and on line between section corners. Found dark hole with wood pieces in natural clay below road layers. The clay line is at 3' deep. The corner falls 0.3' north and 0.8' west of J. Kerr iron.

5-19-2006 County Surveyor set 5' telspar pipe down 0.4' at computed location. Corner falls in centerline of CR 102 and 2' south of field drive west.