Certificate of Location of Government Corner

ID#: 723304 **Description:** S 1/4 SEC COR 33 72 **Date Set:** 6/30/2005 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" brass plug with punch mark

Reference Ties:

The corner falls 1.8' north of centerline of CSAH 9 and in line with fence south
County Survey Disk in W side PP #42508 SSE 67.82'
Ground wire near ground level on W side PP #245 N 143.79'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor. West between sections 4 and 33. 40.00 chs. Set post and drove charred stake. Built mound with trench. Planted plumb SE and apple seed NE

5-1880 John Fraser (P. 364 No. 355), County Surveyor found cedar stake.

5-1903 Charles Armstrong (P. 46B), County Surveyor, found red cedar stake with stone beside it. Left as found.

9-1930 John Kerr (B. 3 P. 56) found red cedar stake. Set 2"x12"x18" limestone with glass. Corner falls in line with fences north and south.

7-20-1973 County Surveyor dug away entire road with dozer and found exact corner as described by John Kerr in 1930. Set small iron and more glass.

11-20-1974 County Surveyor set a 1 1/4" pipe as final corner.

6-12-2001 County Surveyor found 1 1/4" pipe at surface in good condition.

7-15-2003 County Surveyor found 1 1/4" pipe at surface in good condition.

6-30-2005 County Surveyor set a brass plug with punch mark at surface from coordinates. Monument falls 1.76' north of centerline of CR 9. Rechecked all ties and updated distances, porch gone, wood stub pole and nail in maple gone.

4-27-2009 County Surveyor found 5/8" brass plug w/punch mark at surface in good condition.