Certificate of Location of Government Corner

ID#: 723306 **Description:** 1/4 SEC COR 32 33 72 **Date Set:** 8/31/79 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.8'
The corner falls 6' north of fence west and 10' east of centerline of N-S twp road
County highway disk in S side PP #266 WSW 42.91'
The corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 32 and 33. 40.00 chs. Set a quarter section post in mound of earth and sod. Deposited charcoal. Made trench and pits. Planted Osage orange seeds East and West of the trench.

1857 E. P. Bircher, Surveyor, and J. B. Fellows, Deputy, (Co.Rd. No. 95) surveyed road between sections 32 and 33.

6-1873 Thomas Hunter, County Surveyor, (Book A, Page 226, No. 229 and Old Field Book 3 Pages 21-22) states: 1/4" post missing and could not be found, the road having been plowed and scraped- We therefore set stake properly marked midway (39.84 chs.) between G (the S.E. Cor. 32) and A (the N.E. Cor. 32) the section corners, but as Mr. Williams, who built the East Road fence stated that he started his fence 29 feet East of the stake (which was then standing). We set the new 1/4 post that distance from said fences, which makes quite an angle at H (1/4 Cor. 32-33) in the section line, but old settlers say there always was a big crook in the line at that point." He used the corner to set the 1/16th West midway (20.15 chs.) and on line to the Center 32 which he set at intersecting 1/4 lines. He also measured 40.13 chs. West from Sec. Cor. 28-29-32-33 to 1/4 Cor. 29-32 and 39.99 chs. West from S. Sec. Cor. 32-33 to the S. 1/4 Cor. 32.

5-1880 John Fraser (Book A, Page 364, No. 355) found the stake. Used the corner to set the 1/16th North, the 1/16th East and the Center 33.

1930 John Kerr (Kerr Book 3, Pages 56-57) ran a random line from the N.E. Cor. 32 (found) to the S.E. Cor. 32 (found). The object of this work was to "establish the road line between sections 32 and 33."

11-14-1968 John Kerr (Kerr Book 98, Page 35) set the corner midway and on line between the section corners. Set a C.I.M. as the corner.

8-31-1979 County Surveyor dug East of Kerr's on line corner as indicated in Hunter's Survey No. 229. Found the remains of Hunter's stake 2' deep in the road and .4' North and 13.2" east of Kerr's C.I.M. (removed). Set a C.I.M. over a 1/2"x19" rod driven through the stake as the corner.

CORRECTION OF A CORNER: The correct corner is .4' North and 13.2' East of Kerr's C.I.M. (removed) location.

8-18-2010 County survey crew found CIM down 0.8' in good condition.