Certificate of Location of Government Corner

ID#: 723404 **Description:** S 1/4 SEC COR 34 72 **Date Set:** 7/5/2005 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 12W **Monument Description:** 1" square pipe with cap RLS #15809

Reference Ties:

The corner falls 40' west of centerline of TH 42 and 2' south of centerline of CSAH 9
County Survey Disk in E side PP SW 62.41'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor, West between sections 3 & 34. 40.00 chs. Set post and drove charred stake. Built mound with trench. Planted plumb S.E. and apple seed N.E.

7-16-1973 County Surveyor removed entire road area with dozer and found limestone (broken by dozer blade), glass, and 30"x1-3/8" axle shaft. Referenced and replaced shaft in its hole where torn out by dozer.

11-20-1974 County Surveyor drove 1-1/4" pipe as final corner.

8-6-2003 County Surveyor found 1 1/4" pipe down 0.5' in good condition.

7-5-2005 County Surveyor found iron pipe down 0.5' in good condition, took local ties and removed. Set 1" square pipe w/cap at surface. CSD with concrete nail in east side of PP # SW 62.41' and 23.1' east of concrete.

1-9-2007 County survey crew found 1" square pipe w/cap at surface in good condition.

3-6-2007 County survey crew found 1" square pipe w/cap at surface in good condition.

6-2-2008 County survey crew found 1" square pipe w/cap broken, removed and set new cap.

7-7-2016 County survey crew found 1" square pipe with cap at the surface in good condition.