Certificate of Location of Government Corner

ID#: 723504 **Description:** S 1/4 SEC COR 35 72 **Date Set:** 11/29/1994 **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls in centerline of CSAH 7 south and in centerline of CSAH 9
Punch hole in top of flange on SE end 36" CMP SE 51.0'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 2 and 35. 40.00 chs. Set post for 1/4 section corner. Burr Oak 10 in. S67 1/2°E 228 lks. Burr Oak 12 in. S24°W 53 lks.

6-1874 Thomas Hunter (P.247 No. 248), County Surveyor, found a stone in the center of the road as the corner.

9-1927 county highway department (B.48 P.35) found no stone. Assumed the corner to be the P.I. to thecurve in Co. Rd. #7 and took references.

1953 county highway department (B.207 P.4) took references to P.I.

7-16-1976 County Surveyor dug for Hunter's stone with the backhoe but did not find anything. The road had been cut to clay. Set a C.I.M. over a 1 1/4"x20" light pipe as the corner midway and on line between the N.E. Cor. Sec. 2 and the N.W. Cor. Sec. 2.

10-28-1992 County Surveyor dug down to broken headed CIM 11" deep in blacktop CR #9. Set 60d spike at surface, local ties (hook over 1.00' E and 1.00' N)

5-21-1993 county highway department took grading ties to corner location before construction of CSAH #9.

11-30-1993 county highway department set 3/8" iron at corner location in crushed rock CSAH #9.

11-29-1994 county highway department set 5/8" copper plug in concrete CSAH #9 as final corner.

12-12-2006 County Surveyor found 5/8" copper plug at surface in good condition.

3-6-2007 County Surveyor found 5/8" copper plug down 0.1' in good condition.