Certificate of Location of Government Corner

ID#: 723604 **Description:** S 1/4 SEC COR 36 72 **Date Set:** 11/29/94 **County:** Olmsted

Section: 36 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9 and 20 1/2' east of centerline of residential driveway south
This corner is located by GPS measurement

Corner History:

Gov't Notes 40.00 Not ? B.T.'s Burr Oak 10 N 82 E 110 Burr Oak 8 S 70 W 118

6-1893 W. Fraser P. 517 No. 483 corner gone, no evidence, B trees or knowledge of corner set stone 2-1/2 x 8 x 25 M & L. 39.85 S 89°30'E 1/16 north set stone must be "3" M & L 20.00 2630.1. This corner either stone 2x8x16 or 2 stones 2x9x15 and 2x9x12 - not numbered on plat.

9-1927 County Highway Department B48 P33 stone in place. Sp 24" oak NW 25.9 - 10" oak NNE 22.8.

1935 County Highway Department B75 p.63 found L S 2"x6"x? on end set 80d spike on west side stone, cut cross, 2x2x18 on west side. Spin 24" oak NW 26.6' - 80d in same tree 25.4' nail in f.p. N 36.4'.

1938 county highway department B94 p.3 corner is PI delta 0°8'Rt. going east Sta. 53+00 found limestone with top 2"x6"angle top 1x2 stake on west side stone cross. RH 24" oak NW 26.6. Sp 8" tree br oak NE - 89.58 (84.58? meas. east 2623.7, Sp 12" tree br oak NNE 81.7' meas west 2629.3 R 2630.1 late add

From section work in 36 & 1 in 1992 survey we determined W. Fraser M & L location best fit existing property & monumentation, This area in deep ±20 cut to be worse after grading of CR #9 in 1993.

11-30-1993 county highway department set 3/8" iron in crushed rock CR 9 after construction.

11-29-1994 county highway department set 3/4" copper rod in concrete CSAH #9 as final corner @ M & L location.

11-17-2006 County Surveyor found 5/8" copper plug with punch mark at surface in good condition.

3-6-2007 County Surveyor found 5/8" copper plug with punch mark at surface in good condition.