Certificate of Location of Government Corner

ID#: 730105 **Description:** SEC COR 1 2 11 12 73 **Date Set:** 12/16/2004 **County:** Olmsted

Section: 01 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 3' south of centerline of CR 124, 3' east of centerline of twp road south and 1 1/2' east of centerline of twp road north
County highway disk in PP #19607 SE 54.40'
Punch hole in W end 30" CMP SW 46.00'
Punch hole in W end 48" CMP NW 49.69'
Punch hole in E end 48" CMP NE 49.54'
Ref pipe SE 75.51'
16d spike in PP #42023 SW 64.10'
Ref Pipe SE 75.51'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 80.00 set a section post to 1-2-11-12, made trench. Burr Oak S 11 E 223 links.

5-1872 T. Hunter P.202, No.211, found stake. Set stone 3"x5"x20" as corner. 16 west set stone 3"x6"x15" with cedar stake by its side M&L 19.84 (1309.44). 16 east set stake measure M&L 19.84 (1309.44) (Reset to stake from 1/4 post found by bearing tree stump S891/2 E. Measure north 39.81 (2627.46) to stone set on line & Gov't porp. Measure being 40.41' north to section corner from 1/4 1-2 N 20' east.

7-1902 W. Fraser, P.22B found stone & stake. 16W found stone M&L between A&B, Bearing being stake found as set. P.202 set stone on top of stake. All 1/4 miles 19.89 (1312.74 Hunter 19.87 1311.42).

?? county highway department B. 279, P4 set assumed point for CR 124 survey.

10-9-1972 County Surveyor set nail 1' east of County Highway Department ties. Set nail at 2629.85 R 2627.46 at 1/4 1-2 area. Found stone at 1/4 1-2 .45 south .52' west of nail, final measure north to CIM at N+-2 2672.36 R 2667.06.

6-18-1976 County Surveyor dug for corner, found nothing.

6-20-1976 County Surveyor dug further, found nothing.

9-1-1976 County Surveyor set 1/2"x2' rod as corner doubling line and measure from west.

7-14-2003 County Surveyor removed p.k. nail at surface. Dug down and found 1/2" iron down 1.8'. Removed and set 1" square pipe w/cap at iron location.

5-17-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-18-2004 County Surveyor set reference pipes for 2004 overlay.

8-3-2004 County Surveyor removed 1" square pipe w/cap for 2004 overlay.

12-3-2004 County Surveyor set p.k. nail at surface from 2004 overlay tie-out.

12-16-2004 County Surveyor set 1" square pipe w/cap at surface over pk nail. CSD in pp #19607 SE 54.40' and 16d spike in pp #42023 SW 64.10'.

9-20-2006 County Surveyor found 1" square pipe w/cap in good condition at surface.

1-18-2007 M James Associates found and used monument for survey in SW 1/4 section 1.