Certificate of Location of Government Corner

ID#: 730106 **Description:** 1/4 SEC COR 1 2 73 **Date Set:** 9/20/2006 **County:** Olmsted

Section: 01 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' west of centerline of N-S twp road and 70' south of centerline of field drive east
Chiseled "X" on top inlet apron most northerly pipe of 2 NE 38.09'
Pop cap in PP #19742 SE 79.28'
Ref pipe W 75.36'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 40.00 set temp section post south between Sec. 1&2, 39.7 a stream 3 links wide course NW, 40.6 set a section post in mound, charcoal, trench, pits and planted osage orange seeds E&W of trench.

5-1872 T. Hunter P.202 No. 211, set stake as center at inter lines. 16W set stake M&L 19.90 N 89° 25' W, measure south 39.85 N20'E.

10-9-1972 County Surveyor dug and found the recorded stone 3.5' deep. Set a C.I.M. over the stone.

8-23-1976 County Surveyor found the C.I.M. broken. Removed the broken portion and set a 10" C.I.M. over the remainder.

10-2-1996 county highway department tied out corner for culvert replacement. Set 1" square w/cap as reference 2' north E-W fence, and Centerline Twp rd E 75.5'.

10-21-1996 county highway department set 3/4" rerod down 0.4'. Took new reference points: chiseled x on top inlet apron, most northerly pipe of 2 NE 38.15', pop cap pp #19742 SE 79.15'.

9-20-2006 County Surveyor found 3/4" iron rod down 0.7' in good condition, took local ties. Set 4' telspar pipe w/CIC over iron rod down 0.4'. Monument falls 2' west of centerline of N-S road. Pop cap in PP #19742 SE 79.28' and chiseled "X" on top of inlet of pipe NE 38.09'. Did not try to find reference pipe, overgrown.