Certificate of Location of Government Corner

ID#: 730204 **Description:** 1/4 SEC COR 2 11 73 **Date Set:** 12/16/2004 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 124 and 11' east of centerline of field drive north
County Survey Disk in E side 30" Pine S 51.50'
County Survey Disk in NE side PP #19625 SE 52.90'
Punch mark in W end 18" CMP SW 67.37'
Ref pipe NNE 25.49'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby 1853, 40.00 set temp section post west on true line between section 2&11 8° 59' east. 39.991/2 set section post. 10" Burr Oak N33 E169 links. 9" Burr Oak S18 E235 links.

5-1872 T. Hunter P.202 No.211, no corner found, ran & measure section line. Set marked stake M&L 39.74 (2622.84). Measure north 39.86 (2630.76), 16 east set stone & stake by side. Stone is 3"x6"x15" set M&L 19.87 (1311.42).

7-1902 William Fraser, P22B, found stake P.202 M&L 39.78 (2625.48'). Set stone on top of stake. 16 east found stone P.202 M&L 19.89 (1312.74). 16 west set stone M&L 19.89 (1312.74), stone size 3"x5"x14".

1963 county highway department Book 279 Page 2 assumed corner location for P.I.

8-20-1976 County Surveyor at 1/16th corner east found 3" x 0/10" x 15" stone. Set pipe on north and south sides with 1/2" x 2' rod at road surface.

8-20-1976 County Surveyor found stone. Set 1/2"x2' rod at surface & drove shaft along side. Corner 1' North of centerline.

9-1-1976 County Surveyor took Rp's. (See above).

6-23-2003 County Surveyor found p.k. nail at surface, took local ties and removed. Found 1/2" iron rod down 2.0' lying on its side. Removed 1/2" iron rod and patched hole with blacktop.

6-30-2003 County Surveyor set 1"x2' square pipe w/cap #15809 at surface from local ties of p.k. nail.

5-17-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-18-2004 County Surveyor set reference pipe for 2004 overlay.

8-3-2004 County Surveyor removed 1" square pipe w/cap for 2004 overlay.

12-3-2004 County Surveyor set p.k. nail at surface from 2004 overlay tie-out.

12-16-2004 County Surveyor set 1" square pipe w/cap at surface over pk nail. CSD in pp #19625 SE 52.90' and CSD in 30" pine south 51.50'. Did not check other ties.

9-20-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.