Certificate of Location of Government Corner

ID#: 730205 **Description:** SEC COR 2 3 10 11 73 **Date Set:** 12/16/2004 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 124 and in line with fence north
County highway disk in PP #19642 SSW 51.97'
County highway disk in 24" Pine NE 63.15'
Ref pipe NNE 46.58'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 80.00 set section corner post. 9" Burr Oak S 121-1/2 E119 links, 9" Burr Oak S 8-1/2 W132 links.

5-1872 T. Hunter P.201, No.210 found stone. 16 South set stake M&L 19.97 (1318.02).

5-1872 T. Hunter 202, No.210 found stone P.20 tested by Bearing tree, in good condition. Measure east 39.74 to stake set M&L 2622.84.

7-1902 W. Fraser, P.22B found stone. 16 S set stone M&L 19.99 (1319.34). 16 E set stone 3"x5"x14" M&L 19.89 (1312.74).

1932 county highway department Book 72 Pg. 26 found stone monument.

1963 county highway department B.279 P.2, found stone. Set CIM over stone.

11-1964 J. Kerr found CIM, rechecked references: Disc pp SSW 52.01. Disc pine NE 63.31'. Disc Elm NNE 46.26'. 1" pipe by 2x2 hub & disc N 66.4'. Sta. 26+24.95 from 1/4 3-10 found 3x3 stone with a PI 0° 5' lt. Going east. Measure east to assume corner as 1/4 2-11 (2608.22 R2625.48).

11-17-1969 J.Kerr, at 1/16th corner south found stone.

7-3-2003 County Surveyor found CIM down 1.2'. Took local ties and removed. Filled with blacktop ready for 1" square pipe.

7-14-2003 County Surveyor set 1" square pipe w/cap at surface from local ties.

5-17-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-18-2004 County Surveyor set reference pipe for 2004 overlay.

8-3-2004 County Surveyor removed 1" square pipe w/cap for 2004 overlay.

12-3-2004 County Surveyor set p.k. nail at surface from 2004 overlay tie-out.

12-16-2004 County Surveyor set 1" square pipe w/cap at surface over pk nail. county highway department in pp #19642 south 51.97' and county highway department in 24" pine NE 63.15. Did not check any other ties.

10-25-2005 County Surveyor found 1" square pipe w/cap at surface in good condition. Found 1" pipe to the north laying flat, removed. Elm to the north ok but tie gone.