Certificate of Location of Government Corner

ID#: 730304 **Description:** 1/4 SEC COR 3 10 73 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 03 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11 and in centerline of CR 124 east
The monument is down 0.9'
County highway disk in PP #19655 SE 52.50'
County highway disk in PP #19656 SW 54.18'
County highway disk in NE side PP #19657 NW 45.55'
Ref pipe WSW 125.62'
This corner is located by GPS measurement

Corner History:

Gov't Notes, Yerby - 40.00 set temporary section post west on true line between section 3&10. 40.04 set section post 9° 03' E. 8" Burr Oak N30 E110 links, 15" Burr Oak S65 W87 links.

5-1872 T. Hunter P.201, No.210, found stake. Set stone 3"x8"x16" in place of stake. 16 west set stake M&L 19.931/2 (1315.71). 16 south set stone M&L 19.94 (1316.04). 16 center NW1/4 10 set stake at inter lines.

5-1873 T. Hunter P.223 No.226, found stone set P.201. 16 north set stake M&L 19.92.

4-2-1953 county highway department found stake & limestone. Set 8"x8"x30" conc. Marker (BK 198).

11-1964 J.Kerr found 8"x8"x30" concrete monument. Removed concrete monument. Set CIM over 3/8"x18" steel rod.

6-8-1994 County Surveyor found CIM in good condition. Set 1" square pipe w/cap as ref. 13' South of centerline CR#124 125' west of centerline CR 11. On C.R. #11 removed CIM before cold reycling bituminous project.

11-14-1994 county highway department set 1" square pipe w/cap at surface from 1994 overlay tie out.

5-17-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

10-17-2005 County Surveyor found 1" square pipe w/cap at surface in good condition. Updated all ties and distances.

5-23-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.