Certificate of Location of Government Corner

ID#: 730305 **Description:** SEC COR 3 4 9 10 73 **Date Set:** 10/21/2005 **County:** Olmsted

Section: 03 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of centerline of CR 124 south and 1/2' north of centerline of CR 124 east
County highway disk in PP #34724 SE 47.46'
County highway disk in PP #34722 SW 46.82'
County Survey Disk in SE side PP NE 47.45'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 80.00 set section corner post. Burr Oak 4" N32 W224 links, Burr Oak 12" N 49 E60 links, Burr Oak 12" S12 E98 links, Burr Oak 13" S65 W147 links.

5-1872 T. Hunter P.201, No.210, found stake, tested 1 bearing tree standing & stumps of others.
16S set stake M&L 19.94 (1316.04). 16E set stake M&L 19.931/2 (1315.7). 16C set stake inter lines.

5-1873 T. Hunter P.223, No.226, found stake P.201. 16 north set stake M&L 19.88 (1312.08').

12-1932 county highway department B.72, P.23 - found stake

1940 J. Kerr set 1 1/2" pipe.

7-1964 J.Kerr, corner 1 1/2" pipe found. Set CIM over pipe.

11-7-1983 Vince Fangman found CIM in good condition. Used in survey in sec. 9

4-23-1986 Vince Fangman found CIM in good condition. Used in survey in sec. 9

11-10-1989 Roger Brand found CIM in good condition. Used in survey in sec. 9

8-23-1990 Roger Brand found CIM in good condition. Used in survey in sec. 9

8-1996 Peoples Coop found 1" ± pipe with top pushed over WSW, about .4' deep.

2-8-1999 County Surveyor found 1" pipe/cap bent. Straightened pipe and reset.

10-21-2005 County Surveyor found 5/8"x4" iron rod down 0.3', took ties and removed. Found CIM down 1.2' in good condition, took local ties and removed. Found 1 1/2"x3' iron pipe down 3.0' in good condition, took local ties and removed. Set 7' telspar w/CIC down 0.55' from ties taken from CIM. Updated all ties. CSD with concrete nail in SE side of PP no # NE 47.45'.