Certificate of Location of Government Corner

ID#: 730306 **Description:** 1/4 SEC COR 3 4 73 **Date Set:** 10/25/2005 **County:** Olmsted

Section: 03 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.6'
County highway disk in PP SW 54.22' (leaning)
County Survey Disk in W side PP SE 74.48'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 40.00 set temp sec post south 18' E on true line between section 3&4. 40.95 set a section post in mound, with charcoal, trench, pitts, and planted osage orange E&W of trench.

5-1873 T. Hunter, P.223, No.226, found stake. Set sandstone below surface 6"x8"x24". 16 south set stake M&L 19.98 (1312.08"), used corner to set center (No. road here in 1873).

11-1964 J. Kerr, found stone. Run aerial line N&S (corner 2.6' east of direct line). Measure s 2626.8' to SW cor. 3 R2624.16.

5-22-1965 J.Kerr set CIM over 2"x40" pipe & stone.

8-1996 Peoples Coop found CIM about 0.8' deep.

10-25-2005 County Surveyor found CIM leaning SE, took ties and removed. Found 2" pipe down 2.9', took local ties and removed. Set 5' telspar w/CIC down 0.5' from ties taken from pipe. CSD w/60d nail in west side of PP no # SE 74.48'. CSD w/concrete nail in south side of wooden corner post east 53.56', PP to the NE gone, bridge replaced by culvert, PP to the SW abandoned and leaning and bridge sign gone.

9-7-2011 County survey crew found telspar pipe and cast iron cap with the top 1' bent. Removed and replaced with a new 5' telspar pipe with cast iron cap.