Certificate of Location of Government Corner

ID#: 730404 **Description:** 1/4 SEC COR 4 9 73 **Date Set:** 11/8/1983 **County:** Olmsted

Section: 04 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is up 0.2'
The corner falls 35' south of centerline of E-W twp road on curve
RR Spike in 8" Hackberry SW 33.77'
Post w/sign 1' south
This corner is located by GPS reference stations "Kick Off A & B"

Corner History:

1853 Gov't Notes, Yerby - 40.00 set temp section post west on true line between 4&9 9° 00' east. 39.99 set section post. 9" Burr Oak N28 E183 links, 10" Burr Oak S20 E85 links.

11-1964 J. Kerr B.89 P.77, set rod M&L 2634.0.

5-1965 J.Kerr set CIM over 1/2"x2' rod.

5-19-? Pat Patterson reports CIM lying on side in ditch.

11-8-1983 Vince Fangman reset top of CIM over base. Corner falls 35' south of centerline on gravel road. RPs- RR spike in 15" elm SSW 29.95', RR spike in 8" hackberry SW 33.77'.

11-21-1989 County Surveyor found CIM. Set sign & post 1.0' south.

10-17-2005 County Surveyor found CIM along south side of washout area in ditch. Elm tree with tie down, other tie ok, did not check distance.

9-8-2011 County survey crew found cast iron monument with head broken. Removed cast iron monument. Found 1/2" iron rod below. Removed iron rod and replaced it with a 4' telspar pipe with cast iron cap.