Certificate of Location of Government Corner

ID#: 730406 **Description:** 1/4 SEC COR 4 5 73 **Date Set:** 10/22/1976 **County:** Olmsted

Section: 04 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls on SW side CP to fences north and west (corner post gone, remnants of fence still there)
County Survey Disk in E side 1" Cedar NW 62.16'
County Survey Disk in SW side 12" Oak SE 14.29'
Post w/sign 2' west
This corner is located by GPS reference stations "Plank A & B"

Corner History:

1853 Gov't Notes, Yerby, 40.00 set temp section post south 10' East on true line between section 4&5. 41.02 set a section post. Burr Oak 9" S52°E 62 lks. Burr Oak 12" S11°W 60 lks. 81.02 chs. To section corner. 9" Burr Oak S52 E62 links, 12" Burr Oak S11 W60 links.

3-1898 W. Fraser P.620 No.563 found stake & stump of SE Bearing Tree, Drove new stake and set stone 2"x6"x24" by its side. 16N set stake & stone on section line and north. 20.09' then 21.11' (1393.26 to iron set a corner).

9-24-1976 County Surveyor, 1/16 north, found limestone 3"x10/16" x 34' leaning.

9-27-1976 County Surveyor dug for the corner. Found the spot where an old post had stood on the South side of the present corner post.

10-22-1976 County Surveyor at 1/16th corner north straightened stone. Stands 1'W fence.

10-22-1976 County Surveyor set CIM over 1/2"x2' rod as corner.

10-18-2005 County Surveyor found CIM up 0.1' in good condition. Corner post gone but fences remain. Tie in Burr Oak gone all other ties in good condition, did not check ties. Set sign and post 2.0' west.