Certificate of Location of Government Corner

ID#: 730504 **Description:** 1/4 SEC COR 5 8 73 **Date Set:** 10/19/2005 **County:** Olmsted

Section: 05 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

+ punch mark SSW side (up 15") stave silo NW 108.82'
+ punch mark NE side (up 15") stave silo NW 107.88'
County Survey Disk in NW side 66" Cottonwood ENE 85.20' (tie grown over)
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 set temp section post west on true line between sec. 5&8 8° 09' E. 40.031/2 set a section post. Burr Oak 8" N50°W 228 links. Burr Oak 12" S25°E 213 links. 80.07 chs. To section corner.

3-1898 W. Fraser P.620, No.563 corner post avered by Simmonds, set stone 3"x6"x14 beside post & stake, no measurement or 1/16 corner.

9-24-1976 County Surveyor found stake, Set 2"x40" pipe w/steel post. Set CIM over 3/4" x 22" pipe over 2" pipe. Removed stake to office. Spike & CSD NW side 51/2' Cottonwood along side ditch ENE 85.20'.

11-13-1989 County Surveyor found CIM in good condition with two steel fence posts around. Pulled one post, set sign and post 1' south.

10-19-2005 County Surveyor found CIM leaning with head broken off, took local ties and removed. Found 3/4" pipe down 1.5', took local ties. Set 4' telspar pipe w/CIC over 3/4" pipe up 0.3'. Tie in Cottonwood grown over. Found punch marks in silo but unable to recheck because of new landscaping.