Certificate of Location of Government Corner

ID#: 730506 **Description:** 1/4 SEC COR 5 6 73 **Date Set:** 10/22/1976 **County:** Olmsted

Section: 05 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3' north of easterly post in group of three at fence intersection.
30d Spike in 10" Cherry ESE 9.4'
30d Spike in 8" Pine SE 21.0'
Post w/sign 2' north
This corner is located by GPS reference stations "Tilford A & B"

Corner History:

11-1853 Gov't Notes W.B. Yerby, Deputy Surveyor South on true line between sections 5 and 6. 40.40 chs. Set a quarter section post in a mound of stone. 40.70 chs. Descend a Bluff. 80.70 chs. To Section Corner.

3-1898 William Fraser (P. 620 No. 563), found a stake in a pile of stones as given in the U.S. Gov't Field Notes. Set a stake at the 1/16th North. Also set the Center Sec. 5.

4-1901 William Fraser (P.5B) found the corner P. 620.

1964 John Kerr, County Surveyor, searched for the corner but could not find it.

9-27-1976 County Surveyor dug for corner at 1/16th north (found nothing).

9-27-1976 County Surveyor dug for the corner but found no evidence of the corner.

10-22-1976 County Surveyor set a C.I.M. over a railroad spike driven in bedrock as the corner at the intersection of the line from the East 1/4 Cor. 5 over the Center sec. 5 (found) and the main line of the fence North.

12-22-1997 McGhie & Betts Found monument inplace and took new references.

11-18-2002 County Surveyor found CIM at surface in good condition. Set post w/sign 2.0' North.