Certificate of Location of Government Corner

ID#: 730604 **Description:** 1/4 SEC COR 6 7 73 **Date Set:** 4/11/2005 **County:** Olmsted

Section: 06 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with N-S fence and in line with E-W fence
State Reference Point in PP #34070 SW 1.15'
State Reference Point in gate post N 21.60'
County Survey Disk in E side PP N 23.36'
Sign on PP 1' SW
This corner is located by GPS reference stations "Clement A & B"

Corner History:

11-1853 Gov't Notes, W.B. Yerby, Deputy Surveyor East on true line between sections 6 and 7 38.16 chs. Set a quarter section post in mound of earth and sod deposited charcoal made trench and pitts planted osage Orange seeds N and S of trench.

6-1857 Thomas Hunter (Pg. 33, No. 53) used corner and chained east 20.01 then 20.01 to section corner, chained west 20.00, chained south to center of section 39.70 bearing of N0º22'W.

4-1858 Thomas Hunter (Pg. 53, No. 77) used corner chained north 19.88 then 19.88 to center of section 6 on a bearing of N0º05'E.

7-1891 Thomas Fraser (Bk. 7, Pg. 103) use corner chained north 19.88 then 19.88 to center of section 6, stake on west side of stone as set by Hunter, left as found.

4-1901 William Fraser (Bk. B. Pg. 5) did not find any corner.

1972 McGhie & Betts set 3/4" galvanized pipe as quarter corner sixteenth corner north set 5/8" pipe/cap 1313.84 then 1313.85 to center of section 6.

1974 W.H.K.S. found and used pipe set by McGhie & Betts.

3-24-1978 MnDOT found 3/4" pipe up 6" leaning took ties.

4-3-1990 County Surveyor set telspar pipe with cast iron cap in place of 3/4" galvanized pipe set by McGhie & Betts in 1972.

12-18-1997 McGhie & Betts corner had been destroyed but found 2 ties still remaining. Contacted County Surveyor for replacing.

11-18-2002 County Surveyor found telspar pipe w/CIC up 2.0' and bent, removed remaining 1.5' that was still in the ground. Set 2 points to GPS and replace.

4-29-2004 County Surveyor set 120d spike at surface from ties.

4-11-2005 County Surveyor set 5' telspar with CIC up 0.3' from computed coordinates. S.R.P. in pp #34070 SW 1.15', S.R.P. in east side of gate post for fence north, north 21.60' and CSD with concrete nail in east side of pp (no #) north 23.36'. Set sign in pp.