Certificate of Location of Government Corner

ID#: 730606 **Description:** W 1/4 SEC COR 6 73 **Date Set:** 11/27/2002 **County:** Olmsted

Section: 06 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

30d spike in 30" Cottonwood NNE 14.37'
Minnesota Highway Department Brass Nail in 36" Cottonwood NE 18.38'
Post w/sign 2' south
This corner is located by GPS reference stations "TR A & B"

Corner History:

1853 Gov't Notes, John Ball 40.00 set quarter section post Burr Oak 14" N 3 W 244 1KS

6-4-1883 Tom Hunter Pg 383 No. 374 Corner missing but set a boulder stone and stake from one witness tree and in line of the fence west. 1/16 corners north and south.

10-31-1947 John Kerr Set a 1/2" rod by the fence post.

4-19-1979 County Surveyor Measured and dug at many of the 1/16 corners along the township line and found a 5" x 9" x 24" limestone 8.3' South and .5' West of the 1/2" iron being used. A large Burr Oak was also tested as a Tom Hunter Bearing tree. This location did not match the records for the 1/16 corners.

6-21-1988 County Surveyor decided the 1/2" iron rod should be perpetuated as the 1/4 corner because the stone found was not the recorded boulder set by Tom Hunter.

12-18-1997 McGhie & Betts found 1/2" rod inside the concrete footing for an old cedar post. Concrete footing is 12" below ground. Took new reference ties.

11-27-2002 County Surveyor found 1/2" iron rod up 0.2'. Removed 1/2" x 3' iron rod. Set 4' telspar w/CIC up 0.4'. Set sign & post 2.0' South of corner.

10-20-2010 Brian Veronen, MNDOT LSIT, found cast iron cap on telspar pipe in good condition and checked ties.