Certificate of Location of Government Corner

ID#: 730804 **Description:** 1/4 SEC COR 8 17 73 **Date Set:** 4/5/1990 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of CP to fences north and east and 32' east of centerline of N-S driveway
County Survey Disk in PP #47286 SW 31.87'
County Survey Disk in brace post E 8.84'
County Survey Disk in CP N 1.22'
Sign on CP 1' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 set temp sec post west between 8 & 17 8° 42' east. 39.951/2 set section post in mound, charcoal, made trench, pitts, and planted osage orange seed N&S of trench.

5-1894 W. Fraser P.549, No.507 Robinson, Mahon corner couldn't be found. Set stone & stake as corner M&L 40.24. 16 west set stake M&L 20.12. 16S set stake M&L 19.90.

4-1963 J. Kerr found stone, set CIM in its place.

4-5-1990 County Surveyor found CIM W broken top & Leaning. Straightened & took ref. Pulled CIM and set 5' telspar/CIC. Survey sign on South side of C.P.

10-19-2005 County Surveyor found telspar pipe w/CIC at surface in good condition. All ties still there but did not check distances.