Certificate of Location of Government Corner

ID#: 730805 **Description:** SEC COR 7 8 17 18 73 **Date Set:** 8/15/1980 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' south of E-W fence
County Survey Disk in NE side 20" Burr Oak S 93.92' slope
County Survey Disk in NW side 35" Burr Oak SSW 109.51' slope
County Survey Disk in S side 6" Elm E 34.29'
Post w/sign 3 1/2 north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes - Yerby, 80.00 set section corner post, made trench. 12" Burr Oak N16 E327 links. 12" Burr Oak S10 E124 links. 8" Burr Oak S18 W77 links.

2-1858 T. Hunter Pg. 49, No.72 - 1/16 W 19.97 chains M&L to 1/4 post.

4-1864 P.C. Compton Pg.80, No.120, 1/16 West set with Bearing Tree (14" Burr Oak S72° W 52 links.)

10-1877 T. Hunter P.322, No.316, found corner, SW bearing tree standing, SE Bearing tree stump marked. 16N set temp stake M&L 20.05.

8-1893 W. Fraser, P.526 No.497 - found stake P.322, drove new stake. Measure south 39.87 to stone M&L.

5-1894 W. Fraser P.549, No.507, found stake P.526. 16 east drove stake M&L 20.12. Measure south 39.87.

1949 John Kerr, County Surveyor, (Kerr Book 44, Pages 13 and 14) "used fence post" for a survey in the S.E. 1/4 section 7.

1963 Kerr (Kerr Book 86, Pages 55,56,57) shows "1" pipe in bog at F. Cor." Measured North 2662.45 to the C.I.M. set in place of stone at 1/4 Cor. 7-8.

1968 county highway department Book 341 found iron pipe.

4-1974 County Surveyor found pipe standing in bog--old corner post now laying down.

8-7-1980 County Surveyor found stake hole (1/16 east).

8-12-1980 County Surveyor dug for this corner but found nothing.

8-15-1980 County Surveyor set CIC on 6' telspar pipe at intersection of section lines from south and east. This corner falls 7.38' north and 1.00' west of pipe previously found.

12-17-2003 County Surveyor found cast iron cap on telspar pipe up 2.5' in good condition.