Certificate of Location of Government Corner

ID#: 730906 **Description:** 1/4 SEC COR 8 9 73 **Date Set:** 10/26/2005 **County:** Olmsted

Section: 09 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2 1/2' south of centerline CR 124 and 1' east of fence north
County Survey Disk in PP #34770 NE 136.71'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 set section post. 8" Burr Oak N40 W144 links. 6" Burr Oak N25 E312 links.

7-2-1870 Thomas Hunter, County Surveyor, (Hunter's Old Road Book Field Book) used this corner for a road survey for Haverhill Twp. He measured 39.84 chs. East to the center 9 and then 39.68 chs. To the East 1/4 Cor. 9. He measured 40.00 chs. West to the center 8.

1932 County Highway Department (C.H.D. Book 72) assumed corner here.

?? 11/4" pipe used as corner, set M&L 2630.95' by J. Kerr some years ago.

10-1953 John Kerr, County Surveyor, (Book 58 Page 61) ran the line from the N.E. Cor. 8 to the S.E. Cor. 8. He shows a 1 1/4" pipe at the corner and measurements North and South of 2630.95'. He ran the line West from this corner to the West 1/4 Cor. 8 for a survey in the NE 1/4 Sec. 8.

1959 McGhie's used this corner to set a 5/8" rod on the E-W 1/4 line of Section 8 at the old fence corner near the center 8.

9-1960 J. Kerr (Book 60 Page 3) found the property corners of his 1953 survey and used them for another survey in the NE 1/4 Sec. 8.

10-1963 J. Kerr set CIM over pipe. Corner comes in center road running E&W & 1' west of fence north. Measure west 1 mile 5271.82' N&S 2630.95' rod set as SW corner REA tower tract near where road turns SW'ly at 1714.58'.

11-1964 J. Kerr Book 88 Pg. 70 shows note on E-W 1/4 line AZ. in sec 9.

5-1965 J. Kerr Book 89 Pg. 77-79, Used corner to set center 9. Measure shows from 1/4 corner 8-9 N-2636.6 - 15.28 = 2621.32.

5-9-1979 County Surveyor hit frost at 3' deep, filled hole will dig again.

5-21-1979 County Surveyor attempted to dig for the original corner but there was still too much frost in the road to dig.

8-30-1979 County Surveyor found remains of stake. Drove 1/2"x9" rod at stake location and stood remains along side. Set CIM over 1/2" rod. Removed Kerr's CIM.

11-6-1989 County Surveyor found CIM with broken head. Tele pole SE gone. Chained 136.71 NE to CSD in pp#34770.

2-8-2001 Yaggy Colby found CIM with head broken off.

10-26-2005 County Surveyor found CIM with head broken off down 1.3'. Took local ties and removed. Found 1/2" rod down 2.8' in good condition, ties matched CIM. Set 5' telspar w/CIC down 0.5' at CIM location over 1/2" rod. CSD in PP #34770 NE 136.71'