Certificate of Location of Government Corner

ID#: 730909 **Description:** SEC CEN 9 73 **Date Set:** 11/7/1983 **County:** Olmsted

Section: 09 **Township:** 107N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
3/4" pipe w/cap RLS #14888

Reference Ties:

This corner is located by GPS reference stations "Lyric A & B"

Corner History:

11-24-1964 J. Kerr B.89 P.77 Timm & Kroenig (Dist. Court Case) Set nail at inter lines.

5-4-1965 J.Kerr set CIM over 5/8"x18" rod. Measure east to CIM (found stone) 2627.7. Measure west to CIM, pipe found, set M&L 2626.9. Measure south to 1/4 corner CIM set M&L 2637.93.

3-20-1979 County Surveyor found CIM OK.

8-30-1979 County Surveyor, CIM no longer on E-W 1/4 line after correcting the W1/4 corner section 9.

11-7-1983 Vince Fangman set 3/4" pipe w/cap #14888 at intersecting quarter lines. Corner falls 1.42' south and 0.60' east of CIM in place. CIM is incorrect because we moved the W 1/4 corner 2.68' south.

4-23-1986 V. Fangman found and used 3/4" pipe.

11-21-1989 County Surveyor found CIM and 3/4" pipe. Removed CIM, left iron below in place.

7-17-1990 R. Brand & Associates found and used 3/4" pipe.

4-12-1995 Roger Brand & Associates found and used 3/4" pipe at center of section 9.

10-20-1998 Roger Brand & Associates found and used 3/4" pipe at center of section 9.

10-27-2005 County Surveyor found 3/4" pipe set by V.F. leaning WNW down 0.5'. Pulled pipe and dipped below, believe Kerr's rod down deep. Removed and straightened V.F. pipe.

10-28-2005 County Surveyor set GPS reference Pts. "Lyric A&B", shot straightened V.F. pipe and did not dig for Kerr's rod which is believed to not be there. Both poles with ties have been replaced.