Certificate of Location of Government Corner

ID#: 731004 **Description:** 1/4 SEC COR 10 15 73 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 10 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11 and 1' south of fence west
The monument is down 0.8'
1/2" rod W 99.94'
Ref pipe W 50.97'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 40.00 set temp section post west on true line between sec 10&14 8° 56' East. 39.97 set section post. 9" Burr Oak N40 W181 links. 15" Burr Oak S30 E187 links.

5-1872 T. Hunter, P. 201 No. 210, found stake from SE Bearing tree standing, 16N set stone M&L 19.961/2.

7-1902 W. Fraser, P. 22B found stake. Set stone in its place. Measure east to SW corner 39.74.

1930 county highway department Book 58 P.2, Found corner stone 4"x8".

8-1966 J. Kerr found concrete monument, original stone below. Set CIM on top.

6-8-1994 County Surveyor found CIM. Reference corner before cold recycling bituminous surface of C.R. #11. Removed CIM.

11-14-1994 county highway department set 1" square pipe w/cap from 1994 reference.

10-26-2005 County Surveyor found 1" square pipe w/cap at surface in good condition. Did not check any ties.

5-23-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.